# This Page Is Inserted by IFW Operations and is not a part of the Official Record

## BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.



Appln No. 10/754,938 Amdt. Dated May 19, 2004 Preliminary Amendment

2

#### Amendments to the Specification:

The paragraph beginning at Page 10, please insert new line 30 as follows:

Figure 63A Timers sub-block partition diagram

The paragraph beginning at Page 10, please insert new line 32 as follows:

Figure 66 is a schematic of a timing pulse generator

The paragraph beginning at Page 16, line 5, to be amended as follows:

Figure 278 is intentially omitted shows power on reset

The paragraph beginning at Page 18, line 39 to be amended as follows:

Figure 388A shows setup for multiple preauth fields

Appln No. 10/754,938 Amdt. Dated May 19, 2004 Preliminary Amendment

3

### **Amendments to the Drawings:**

Please delete Figure 413 on page 331 of the drawings and insert Figure 278 on page 237 of the drawings.